SWIN
SWMB
SWOUT
UPS


L1 L2 L3
TO INPUT UPS
L1 L2 L3 N
FROM OUTPUT UPS
L1 L2 L3 N
MAINS
L1 L2 L3 N
LOAD
REMOTE MAINTENANCE BYPASS (NORMAL CLOSE CONTACT)